



## ZC96 4...20mA

ZC96 4...20mA, Process indicator

Code: M12531. [CONSULTAR DISPONIBILIDAD](#)

- > Scale: 240° P1
- > Accuracy: 1,5
- > Full scale: 4...20 mA
- > Modules: 96x96

### Description

- Does not need an auxiliary power supply.
- DIN boxes with dimensions 48, 72, 96 and 144 mm.
- Precision class 1,5
- Measurement in D.C. of 0 ... 10 V, 0/4 ... 20 mA, .../60 mV
- Exchangeable scales for BC48, BC72, BC96, BM 45

### Application

For the measurement of the mean value of voltages and currents in direct current circuits, even of the pulsating type, in a vast margin of values.



## ZC96 4...20mA

Process indicator

Code: M12531.

### Specifications

#### Mechanical characteristics

|                                  |                     |
|----------------------------------|---------------------|
| Size (mm) width x height x depth | 96 x 96 x 49.2 (mm) |
| Fastening                        | Panel               |
| Weight (kg)                      | 0,314               |

#### ZC

Process indicators, 240°

| CODE    | TYPE           | Scale   | Accuracy | Modules | Full scale |
|---------|----------------|---------|----------|---------|------------|
| M12523. | ZC72 0...10V   | 240° P1 | 1,5      | 72x72   | 0...10 V   |
| M12521. | ZC72 4...20mA  | 240° P1 | 1,5      | 72x72   | 4...20 mA  |
| M12520. | ZC72 .../60mV  | 240° P1 | 1,5      | 72x72   | .../60 mV  |
| M12533. | ZC96 0...10V   | 240° P1 | 1,5      | 96x96   | 0...10 V   |
| M12531. | ZC96 4...20mA  | 240° P1 | 1,5      | 96x96   | 4...20 mA  |
| M12530. | ZC96 .../60mV  | 240° P1 | 1,5      | 96x96   | ...60 mV   |
| M12543. | ZC144 0...10V  | 240° P1 | 1,5      | 144x144 | 0...10 V   |
| M12541. | ZC144 4...20mA | 240° P1 | 1,5      | 144x144 | 4...20 mA  |
| M12540. | ZC144 .../60mV | 240° P1 | 1,5      | 144x144 | .../60 mV  |

Scales included in the price (\*) The 6-digit code includes the 4 ... 20 mA scale




## ZC96 4...20mA

Process indicator

Code: M12531.

### Dimensions



| Type | Fig. ZC | Fig. EZC | a   | b    | c    | d   | e   |
|------|---------|----------|-----|------|------|-----|-----|
| 48   | 1       | -        | 48  | 44,7 | 61   | 5,2 | 45  |
| 72   | 1       | 1        | 72  | 67,2 | 43,5 | 5,7 | 68  |
| 96   | 1       | 1        | 96  | 91   | 43,5 | 5,7 | 92  |
| 144  | 1       | -        | 144 | 137  | 64,5 | 7,3 | 138 |